South Humber Bank Energy Centre Development Consent Order

South Marsh Road, Stallingborough, DN41 8BZ

Environmental Impact Assessment: Preliminary Environmental Information Report - Volume II

The Infrastructure Planning (Environmental Impact Assessment) Regulations 2017 (as amended)



Applicant: EP Waste Management Limited Date: October 2019



DOCUMENT HISTORY

Revision	PEI Report issue			
Author	Various			
Signed	Kirsty Cobb	Date	October 2019	
Approved By				
Signed	Richard Lowe	Date	October 2019	
Document Owner	AECOM			

Contents

Figure 1.1	Site Location Plan
Figure 3.1	Parts of the Site (Application and Main Development Area Boundaries)
Figure 3.2	Residential Receptors
Figure 3.3	Environmental Receptors within 5 km
Figure 4.1	Indicative Proposed Development Site Layout
Figure 4.2	Ecological Mitigation and Enhancements (Indicative)
Figure 4.3	Comparison of the Consented and Indicative Proposed Development
Figure 7.1	Air Quality Receptors and Diffusion Tube Monitoring Locations
Figure 7.2	Ecological Receptor Locations
Figure 7.3	Annual Mean Maximum NO ₂ Process Contribution, 2015 Meteorological Year
Figure 7.4	Short Term Maximum NO ₂ Process Contribution, 2014 Meteorological Year
Figure 8.1	Noise Sensitive Receptors and Monitoring Locations
Figure 8.2	Predicted Noise Levels at Ecological Receptors - Worst Case Hour 06:00-07:00
Figure 11.1	Potential Viewpoint Locations
Figure 11.2	Landscape Types and Designations
Figure 11.3	Public Rights of Way and Topography
Figure 11.4	Zone of Theoretical Visibility (ZTV)
Figure 11.5	Final Viewpoint Locations
Figure 11.6	Viewpoint 1 – Farmshop Hotel, A180 (Summer)
Figure 11.7	Viewpoint 2 – Brickfield House (Summer)
Figure 11.8	Viewpoint 3 – Carr Lane Footpath (Summer)
Figure 11.9	Viewpoint 4 – Cress Cottage (Summer)
Figure 11.10	Viewpoint 5 – Beechwood Farm Carvery (Summer)



Figure 11.11	Viewpoint 6 – Sunk Island Footpath (Summer)
Figure 11.12	Viewpoint 7 – Immingham South Footpath (Summer)
Figure 11.13	Viewpoint 8 – Mauxhall Farm Footpath (Summer)
Figure 11.14	Viewpoint 9 – Middle Drain Footpath (Summer)
Figure 11.15	Note: Viewpoint 10 photograph omitted as this viewpoint was discounted from the visual impact assessment (see Appendix 11B, PEI Report Volume III)
Figure 11.16	Viewpoint 1 Farmshop Hotel (North-East), Stallingborough – Photomontage and Wireframe for Indicative Concept Layout
Figure 11.17	Viewpoint 5 Beechwood Farm Carvery (North) – Photomontage and Wireframe for Indicative Concept Layout
Figure 11.18	Viewpoint 7 Immingham South Footpath (South-East) – Photomontage and Wireframe for Indicative Concept Layout
Figure 11.19	Viewpoint 9 Middle Drain Footpath (South-East) – Photomontage and Wireframe for Indicative Concept Layout
Figure 13.1	Heritage Assets within the 3 km and 5 km Study Area
Figure 14.1	Key Watercourses and Flow Direction
Figure 17.1	Cumulative Developments (Short List)



